
Diagnostic Measurements and Condition OMICRON Assessment of High Voltage Bushings

CEPED Conference on Electrical Power Equipment Diagnostics September 2-4, 2015, Kuala Lumpur, Malaysia

Dr. Michael Krüger, OMICRON

#### **Cigre A2.37 Transformer Failure Statistics** 22.000 grid transformers with 150.000 sercice years

#### **Causes for transformer breakdowns**




#### **Bushings = 17,16 %**

Tenbohlen et. al.: "DEVELOPMENT AND RESULTS OF A WORLDWIDE TRANSFORMER RELIABILITY SURVEY" CIGRE SC A2 COLLOQUIUM 2015, Shanghai



# **Cigre A2.37 Transformer Failure Statistics**

#### **External effects of bushing failures**




Tenbohlen et. al.: "DEVELOPMENT AND RESULTS OF A WORLDWIDE TRANSFORMER RELIABILITY SURVEY" CIGRE SC A2 COLLOQUIUM 2015, Shanghai



# **Transformer Oil-Oil Bushings**









### **Transformer Oil-Gas Bushings**



#### EKTG


Application	Transformer Bushing (Oil–Gas)	
Voltage Range	52 kV-1000 kV	
Current Range	Up to 4000 A	
Design	RIP condenser core	
Design	TTF COndenser co	

## LV Bushings of GSU Transformers

**Technical Data:** 

 $U_r = 36 \text{ kV}$ 

 $I_r = 17 \text{ kA}$ 





# **Outdoor GIS-Air Bushings**







# Wall Bushings





# **Generator Bushings**



#### EMH/EKMI

Application	Generator Bushing (Air–Air)
Voltage Range	12 kV–36 kV
Current Range	Up to 36000 A
Design	RIP condenser core



### **Insulation Systems of High Voltage Bushings**





## **Insulation Systems of High Voltage Bushings**







1913 to 1974

since 1950

since 1960

Recommended measures	Time schedule
Visual check – leakage and mechanical damage	In case of maintenance work
Measurement of capacitance and dielectric dissipation factor	<ul> <li>after installation as reference for later measurements (fingerprint)</li> <li>10 years after commissioning</li> <li>dependend on results after each 5 years (uncritical values) or shorter</li> </ul>


Source: B. Heil (HSP Troisdorf, Germany), "Diagnose und Bewertung von Durchführungen", OMICRON AWT Germany 2010



## **Share of Products**

- OIP (65-70%)
- RBP (gering)
- RIP (30%-35%)
- Neu RIS (0%)

- Oil Impregnated Paper
- Resin Bonded Paper
- Resin Impregnated Paper
  - Resin Impregnated Synthetics





# **Resin Impregnated Synthetics (RIS)**

- Craped paper is replaced by a open synthetic textile
- Textile can be impregnated with a filled resin with high viscosity (filler = Aluminiumoxide or Siliciumoxide)
- Filled resin systems are proven to be reliable for use in HV applications for several 10 years
- Improved thermal conductivity and mechanical strength
- No long drying period needed
- Reduced manufacturing time and costs
- Available up to 170kV today







# **Resin Impregnated Synthetics (RIS)**








#### High Voltage AC Test in the Factory Lower Part in a Oil Filled Vessel














OMICRON

# **Capacitive Bushings (2)**











# Capacitive Bushing of a 123kV CT



### **Measuring and Voltage Tap**




Fig. 4: Power Factor Tap

- 1 Closing and grounding cap
- 2 Measurement electrode
- 3 Insulation tap
- 4 Gasket
- 5 Tap flange
- 6 Bushing flange
- 7 Last layer

Source: Passoni & Villa




Fig. 5 : Voltage Tap (upon request for 245 kV bushings)

- 1 Closing and grounding cap
- 2 Measurement electrode
- 3 Insulation tap
- 4 Gasket
- 5 Filling plug
- 6 Bushing flange
- 7 Connection to internal layer
- 8 Tap external housing



## **Bushing Measuring Tap**







# **Measuring Taps**

IN IN A BURNER



#### MICAFIL

3 1. HLYS ALATA






PAGE 23

# **Measuring Taps**






# Measuring Taps





### Arcing at the Measurement Tap



Source: Norbert Koch "Diagnoseverfahren an Hochspannungsdurchführungen aus Herstellersicht", Diagnoseverfahren an Schaltanlagen und Transformatoren, HdT Essen 2013




# Partly Burned Measurement Tap of a 245kV-RIP Busing





Source: Hubert Goebel GmbH

# Partly Burned Measurement Tap of a 400kV-OIP Busing





Source: Hubert Goebel GmbH

# Diagnostic Methods

	Type of Fault							
	Moisture							
	Ageing							
	Contact problems and high impedance							
	faults between layers							
	Shorted grading layers							
	Leakage							
	Partial discharges		,					
	Diagnostic Technique							
	Visual Inspection	OIP	5	1	5	5	5	5
General		RBP	5	1	5	5	5	5
		RIP	5	1	5	5	5	5
Ger		OIP	4	5	4	3	4	5
0	Thermography	RBP	4	5	4	3	4	5
		RIP	4	5	4	3	4	5
Electrical Basic	Capacitance	OIP	5	4*	1	3	4	4
		RBP	5	4*	1	3	4	4
		RIP	5	4*	1	3	4	4
	DF/PF	OIP	3	5	3	1**	2	2
		RBP	3	5	3	1**	2	2
		RIP	3	5	3	1**	2	2
	Dielectric Response with FDS / PDC	OIP	3	5	1	1	1	1
<u> </u>		RBP	3	5	1	1	1	1
nce.		RIP	3	5	1	1	1	1
Electrical Advanced	Partial discharge measurement	OIP	1	5	3	1	5	4
		RBP	1	5	3	1	5	4
		RIP	1	5	3	1	5	4
	Dissolved gas analysis		1	5	1	1	4	5
Ōİ	Moisture in oil		5	5	4	5	3	1
	DF/PF		4	5	4	3	2	2
	Conductivity of oil (IEC 61620)	OIP	4	5	4	3	2	2
0	Particles in oil	•	5	5	5	5	2	5
	Analysis of Furanic components		5	5	5	5	1	5
	Test for corrosive Sulfur		5	5	5	5	2	5
	1 Test for corrosive Sullur	<u> </u>	5	3	5	5	2	5

1=very good, 2=good 3=fair 4=poor 5=not applicable

\*big leakages can be detected with hot collar test \*\*DF/PF from 2-12kV



# Infrared Thermography





Fig.13. Measurement indicating poor current path between bushing inner and outer terminal.




## C-Tan δ Progression of a Bushing



Source: Volker Seitz: "Vorbeugende Instandhaltung an Leistungstransformatoren", OMICRON Anwendertagung 2003, Friedrichshafen




# **Bushing Fault**



Source: Volker Seitz: "Vorbeugende Instandhaltung an Leistungstransformatoren", OMICRON Anwendertagung 2003, Friedrichshafen



# **Fault Mechanisms and Diagnosis**




- Partial breakdowns
  - Measurement of capacitance
  - TanDelta measurement
  - PD measurement
- Voids, cracks
  - Measurement of capacitance (RBP)
  - PD measurement
- Contact problems on measurement taps
  - Tan Delta voltage sweep (tip-up test)
- Ageing, moisture
  - Dielectric response measurements
  - TanDelta

Voltage [kV]	No. of layers	% change
123	14	7.1
245	30	3.3
420	40	2.5
550	55	1.8



# **Definitions of Dielectric Losses**



# **Standards**

Туре	RIP	OIP	RBP
Main insulation	Resin	Oil	Resin bonded
	impregnated paper	impregnated paper	paper
	• •	· ·	
DF / tan delta (20°C, IEC60137)	< 0.7 %	< 0.7 %	< 1.5 %
PF cos phi (20°C,	< 0.85 %	< 0.5 %	< 2 %
IEEE C57.19.01)			
Typical new values	0.3-0.4 %	0.2-0.4 %	0.5-0.6 %
<b>PD (IEC60137)</b> at U <sub>m</sub>	< 10 pC	< 10 pC	
1.5 U <sub>m</sub> /√3	< 5 pC	< 5 pC	
1.05 Ü <sub>m</sub> /√3	< 5 pC	< 5 pC	< 300 pC



#### **Cigre WG A2.34 Brochure 445**

#### **Guide for Transformer Maintenance**




 Table 40: Indicative DF/PF Limit Values for Condenser Bushings



#### **RBP** - Bushings

- Not free of cavities Partial Discharges possible also at rated voltage
- Higher dielectric losses can feed to thermal instability
- RPB has cavities and cracks in the paper which are normally filled with the surrounding oil
- Increase of capacitance
- After a longer storage period this oil is running out. The PD level is increasing and the capacitance is getting smaller








## **RBP – Bushings** Cracks

#### in the Insulation




## Measurement on 220kV RBP Bushings (1971)





#### TanDelta 15-400Hz


DF (f) A, B, C



### **RBP Bushing Oil-Filled Cracks** Oil Ingress by Capillare Effect



## RBP Bushing 123kV (1963)



## Micafil UTXF 24 (Drysomic) RBP Bushings




A,B,N humid after wrong storage

C dried


#### **Micafil UTXF 24 RBP Bushings**


A,B,N never used, wrongly stored, C dried




#### **Micafil UTXF 24 FDS Messung**


OMICRON DIRANA - Durchfuehrungen.drax \*












# Bushing has to be exchanged

defective contact on the measuring tap or

defective connection between the innermost layer and the HV conductor or


partial breakdown between layers

## Measurement Tap O.K.





## Innermost Layer was not Properly Connected to the HV Conductor.




## 123kV RBP Bushing






## **Dissipation Factor Measurement**




## **Measurement of the Removed Bushing**






## **Measurement of the Removed Bushing**






#### Faulty Contact on a Head Connection 245kV RBP Bushing



Source: Hubert Goebel GmbH

#### Faulty Contact on a Head Connection 245kV RBP Bushing





## **OIP Bushings**

- Paper of the OIP bushings ages particularly at high temperatures
- Through aging the dielectric losses will increase
   -> this increases the power factor
- Temperature dependent aging decomposes the Paper and produces additional water
   -> this accellerates the aging




# **OIP Bushings** Winding Machine



Source: Trench Brochure "OIP Transformer Outdoor Bushings"






Source: Proposal from OMICRON, GÖBEL and HSP for the Cigre Working Group A2.43 "Reliability of HV Bushings"



#### Tan $\delta$ Dependency on the Temperature


#### Relative $tan\delta$ as function of temperature



Source: ABB: "Bushing Diagnostics and Conditioning" Brochure 2750515-142 en, Ludvika 2000



### C-Tan $\delta$ Dependency on the Temperature



Limits für Measurement Results

a) Capacity:

Voltage Level / Change of Capacitance

≥245 kV	2.3 %
≥362 kV	1.7 %
≥420 kV	1.5 %
≥550 kV	1.3 %
>550 kV	0.8 %

b) tan delta

Normal values are between 0.2 % and 0.4 %

The Temperature Influence can be neglected between 20°C bis 70°C.

Values between 0.4 % and 0.5 %:  $\rightarrow$  Contact HSP

Values > 0.55 % can be an indicator for an internal problem and should be investigated by a DGA

Source: HSP Manual



PAGE 63

#### **Breakdown in a OIP Bushing**



Source: B. Heil, "Diagnose und Bewertung von Durchführungen", OMICRON AWT Dresden 2010



## **OIP Bushing Fault**





## OIP Bushing Fault



Source: Hubert Goebel GmbH


## **OIP Bushing Fault**





#### **OIP Bushing** at the Sharp Edge of the Foil

#### Breakdown



Source: Hubert Goebel GmbH

## **OIP Bushing**




Source: Hubert Goebel GmbH

## 33kV OIP Bushings






# Tan Delta (T) at 50Hz (OIP DF)




Source: ABB, Bushing diagnostics and conditioning


## Tan Delta (f) at 30°C (33kV OIP DF)



## 123kV OIP Bushings TanDelta = f(U)



# 123kV OIP Bushings TanDelta = f(f)





# 123kV OIP DF Corroded Measuring Tap



# Ageing of RIP Bushings

- Partial breakdowns between capacitive layers are rather seldom
- Decrease of the power factor with increasing test voltage can be an indicator for partial breakdowns
- Also defective connections of the measurement layer to the test tap or of the innermost layer to the high voltage conductor may be the reason for a decrease of the power factor with increasing test voltage
- Increase of the capacitance after a partial breakdown between two layers:


• 
$$C_{new} = C_{old} \times n / (n-1)$$

n= number of layers approx. 4-7 kV per layer

# **RIP Bushings**



# **RIP Bushing**





# Partial Breakdown on a RIP Bushing



Source: B. Heil, "Diagnose und Bewertung von Durchführungen", OMICRON AWT Germany 2010



# **Closed Grading Foils** Better design for Very Fast Transients (VFT)





### Breakdown in Oil Causes a Flash-Over in the Earth Lead

#### due to Fast Transient Earth Currents





# Breakdown in Oil Causes a Flash-Over in the Earth Lead

due to Fast Transient Earth Currents





# **Measurement on a 420kV Bushing**





# Measurement of the Capacitance and the Dielectric Dissipation Factor on C1






# Measurement of the Capacitance and the Dielectric Dissipation Factor on C1


#### Kapazität und Verlustfaktor bei U=10kV und f=50Hz UST Messung am Messanschluss mit geerdetem Flansch (Guard)

U PRÜF [V]	I PRÜF [A]	C [F]	VF [%] gemessen
10001,00	1,21E-03	3,852E-10	4,0732



Kapazität und Verlustfaktor bei U=10kV und f=50Hz GST Messung gegen Flansch mit montierter Messanschlusskappe, Messanschluss kurzgeschlossen gegen Flansch


U PRÜF [V]	I PRÜF [A]	C [F]	VF [%] gemessen
10000,00	2,13E-03	6,784E-10	4,0387



GST



# Measurement of the Capacitance and the Dielectric Dissipation Factor on C1





# **Insulation Resistance Measuring Tap against Flange**






## **Partial Discharge Measurement**






### Inception Voltage below 20kV






# Partial Discharges > 2nC at 45 kV











# Measuring Tap





# Measuring Tap





# **Cutted Bushing**






## **Burned Contact Spring**





# Relative Tan $\delta$ Dependency on the Temperature


#### Relative tan $\delta$ as function of temperature



Source: ABB: "Bushing Diagnostics and Conditioning" Brochure 2750515-142 en, Ludvika 2000



## C-Tan $\delta$ Dependency on the Temperature



#### Source: HSP Operation Instruction BAL EKTG03e

#### 5.4 Electrical measurements

Measurements on bushings require experience with measuring equipment, test set up and the interpretation of measurement results.

This is for some part due to the relatively small capacitance values, which are corrupted by the ambient influence of the environment alone. The measurement of the dielectric dissipation factor can be influenced by the voltage feed on the GIS-side by humidity, weather etc.

#### 5.5 Measuring procedures

Mainly the measuring procedures differ by the coupling of the measuring signal. In case of so-called "not grounded" measurements the test voltage is applied to the conductor of the bushing and the measuring signal is taken at the test tap of the bushing.

The "grounded" measuring procedure is applied, if the bushing which has to be measured does not have a test tap. This is not applicable for the bushing type EKTG.

The devices required for the measurement are usually equipped specifically for the measurement of bushings. The measurement methods are described in comprehensive manuals.





#### 5.6 Equipment

Measuring equipment is available from several manufacturers. Data can be found in the internet or enquired at HSP.

#### 5.7 Limits

For the measurement the influence of the ambient temperature has to be taken into consideration. In the diagram on the left side for C and tan delta the variation through temperature is shown. (Fig.24).

For the material RIP, resin impregnated paper there are limit values for the deviation of the capacitance and the dielectric dissipation factor with relation to the "new value". This value is reliably deducted from the reference measurement described under 4.4.

In case the deviations are larger than mentioned in the table below, HSP has to be contacted in any case. When there are very large deviations the bushing may have to be taken out of operation.

Voltage level	C-Deviation
< 123 kV	10 %
≥ 123 kV	5 %
≥ 245 kV	3%
≥ 420 kV	1%
Guide value tan delta	0.004 - 0.006

Operating Instructions BAL EKTG/03e

Visum 01/09 T/fr

Page 15 of 18

HSP - RIP

tan delta = f (T) delta C = f (T)

-20 -10 0 10 20 30 40 50 60 70

°C

80

Fig.24

ž




# 220kV RIP Bushing, Stored Outside





# 220kV RIP Bushing, Stored Outside





# Influence of Humidity –


## for 123kV Bushings with Silicone Coated Composite Insulators Mounted Horizontally





# Influence of Humidity –


for 123kV Bushings with Silicone Coated Composite Insulators Mounted Horizontally





# **Influence of Humidity**


for 123kV Bushings with Silicone Coated Composite Insulators Mounted Horizontally





# **Measurement with Guard**

#### Leakage current is bypassing the meter




# Measurement With High Humidity With and Without Guard





# Measurement With High Humidity With and Without Guard






# **Moisture in RBP and RIP Bushings**

• The oil side of RBP and RIP bushings doesn't need a housing

• Cellulose near to the surface can absorb water, if bushings are not stored properly

 Incoming water, also from the ambient air reduces the dielectric strength – this causes an increase of the dielectric dissipation factor





# Water in RBP and RIP Bushings








**PAGE 109** 

# Measurement of the Dielectric Response with FDS und PDC






# Combined FDS-PDC Measurement on a RIP Bushing







### FDS Results on RIP, RBP and OIP Bushings






## FDS/PDC on a RIP Bushing at Different Temperatures







## **FDS/PDC** with Dry and Wet Surface




Source: G. Kopp, " Measurement of the dielectric response on HV bushings "

### Drying of a 145kV RBP Bushing TanDelta Measurement






# Drying of a 145kV RBP Bushing



#### **High Voltage Test with PD Measurement**



# PD Measurement - Phase Resolved Pattern @ 157kV






## **Separation of PD Sources in 3CFRD**

2.00

10.00 MHz


14.00 MHz

18.00 MHz




PAGE 119


## **PD Measurement Cluster 1**



### **PD Measurement Cluster 2**



## **PD Measurement Cluster 3**



### **Assessment and Interpretation**

Indication	RBP	OIP	RIP
increase of capacitance	oil in cracks or partial breakdowns	partial breakdowns	partial breakdowns
high dissipation factor	partial breakdowns; insulator surface wet or dirty (clean the insulator); ageing of the inner insulation; water in the inner insulation;	partial breakdowns; insulator surface wet or dirty (clean the insulator); ageing of the inner insulation; water in the inner insulation;	partial breakdowns; insulator surface wet or dirty (clean the insulator); ageing of the inner insulation; water in the inner insulation;
dissipation factor is decreasing with increasing voltage	bad potential connections; partial breakdowns	bad potential connections; partial breakdowns	bad potential connections; partial breakdowns
dissipation factor is strongly increasing with increasing temperature	high moisture in the insulation; high degree of ageing	high moisture in the insulation; high degree of ageing	high moisture in the insulation; high degree of ageing
partial discharges	normal, if constant	Discharges produce gasses; Errosion of the cellulose; production of x-wax	partial breakdowns; cracks or voids after electrical or mechanical stress;

michael.krueger@omicron.at

0

**Questions and Remarks?** 

